



Map prepared by authorities (using army engineers) immediately after the earthquake to indicate the sites (in purple) of temporary housing. The temporary housing was built with a 9 month lifetime. These temporary housing sites inevitably became permanent and adversely influenced the layout of the future city development.



US army Quonset huts built after the earthquake.
 Top image: taken in 1974, 11 years after the earthquake.
 Bottom image: taken in 1987, 25 years after the earthquake. Two of these huts had been elevated and joined together to form a small cinema.